

Monitoring Cultural Resources

Monitor For:

Preservation

Protection



Dog Barn

Denali National Park and Preserve

Baseline Information



Headquarters
Historic District



Cultural Resources

How Many Sites?

Where are they?

What Type?

Historical

Archeological

What features make up the site?

Buildings?

Equipment?

Artifacts?

Research

Fieldwork

Archives

Land Records


Historic Photographs

Diaries

Oral History



McKinley Park Station



Little Annie Mine


Applying the Research

Fieldwork



Art Reynolds' Cabin

Yukon-Charley National
Preserve



Site Map

Historical Photographs



Art Reynolds Cabin-1940s



Art Reynolds

[illegible]

A black and white photograph of a man in a hat and plaid shirt standing next to a large dog, possibly a sheepdog, in a rural setting. The dog is standing on a wooden platform or ramp. A wooden barrel is visible in the background.

A black and white photograph showing a section of a wooden fence that has collapsed. A single wooden post is leaning against the remaining fence structure. The fence is situated in a field of tall grass and weeds. A wire fence is visible in the background.

Sled 1986

Monitor for Preservation

Shushana Patrol Cabin



1993
Prior to
Rehab.



During
Rehab.



Monitor for Protection

Shop Building

Aug '99



Sept '99



Mess Hall

Aug '99



Sept '99



Stampede Mine

Pilgrim Cabin

Aug '99



Sept '99



Bunkhouse

Aug '99



Sept '99



Monitoring Cultural Resources

Field work

Baseline information - what do we have?

Research

To determine site significance

- how important is this site?

Monitor

Deterioration, vegetation, and other threats

Management

Accumulated information and research
helps define management actions
preservation and protection.